



TD FREEWAVE DGRD9
DR DGR24

FLOW AUTOMATION
AUTOPILOT



CAUTION - CABLE MUST ROUTE AWAY FROM RADIO
FOR CONNECTIONS TO BE CORRECT.
DAMAGE WILL RESULT IF PLUGGED IN BACKWARD.

<p>FreeWave Technologies Inc. 1880 FLATIRON CT. SUITE F BOLDER, CO 80301</p>		APPROVED BY:	DRAWN BY:
		JH	JH
<p>FREEWAVE TD FLOW AUTOMATION AUTOPILOT</p>		DATE:	8-14-01
CONNECTION DIAGRAM	CONAUTOPILOT	DRAWING NUMBER	REV.